772

PRELIMINARY ASSESSMENT COVER SHEET STEPHENS DRUM STORAGE AREA GAD981471709

I. HISTORY OF SITE

The Stephens Drum Storage Area is located near Lake Blackshear in Sumter County, approximately 2.0 miles east of Cobb Georgia 31735. The property where hazardous wastes were stored is a pecan grove and is owned by Mr. Ed Stephens of Cobb County, Georgia. The owner purchased approximately one hundred and twenty-five 55 gallon drums of wastes (paints wastes) from Warner Robins Air Force Base (TSD facility) at an auction two or three years ago (1983 or 1984). A site investigation was conducted by the Georgia EPD on January 29, 1986.

II. NATURE OF HAZARDOUS MATERIALS

A composite sample from 3 of the drums was collected and laboratory analyses revealed that the sample contained toluene, ethyl benzene, xylenes, methyl ethyl ketone, methyl isobutyl ketone and butyl acetate. Many of the drums were observed during the site investigation to be leaking slightly.

- III. DESCRIPTION OF HAZARDOUS CONDITIONS, INCIDENTS, PERMIT VIOLATIONS

 One hundred and twenty-five (55 gallon) drums were stored in an open area and were found to contain hazardous constituents.
- IV. ROUTES FOR CONTAMINATION

Wastes could have left the site via infiltration into the soil and surface water run-off.

V. POSSIBLE AFFECTED POPULATION AND RESOURCES

The population distribution within one, two and three mile radii of the site is 403, 1,079 and 2,257 respectively.

VI. RECOMMENDATIONS AND JUSTIFICATIONS

This site is assessed a "None" priority for a Site Inspection because on September 25-27, 1986, the Environmental Protection Agency performed a removal of all drums, wastes and residual contamination.

VII. REFERENCE TO SUPPORTING DATA SOURCES

- Complaint Record, 1/24/86.
- 2. Georgia EPD Trip Report, 1/29/86.
- 3. Georgia EPD Laboratory Report, 4/1/86.
- 4. Telephone Memorandum, 2/5/86.
- 5. Record of Telephonic Conversation, 10/17/86.
- 6. Site Inspection Fact Sheet, 3/14/86.
- 7. Memorandum, 2/21/86, RE: Ownership and Laboratory Analysis.

GAKmcw020

File - Stephens Drum Storage Area (GAD981471709)

€EPA	Į.	NTIAL HAZ PRELIMINAF SITE INFORM	RY ASSE	SSMENT		I. IDENTIF	CATION SITE NUMBER 0981471709
II. SITE NAME AND LOCATION				110 A33E337	MENI		
01 SITE NAME (Legal, common, or descriptive name of			02 STRE	ET, ROUTE NO., C	R SPECIFIC LOCATIO	N IDENTIFIER	
Stephens Drum Storage	Area			e Blacksh			
Cobb				05 ZIP CODE 31735			07COUNTY 08
O9 COORDINATES LATITUDE 31°_57'12,5" O DIRECTIONS TO SITE Starting from nearest public	madi	5' <u>22.</u> 5"					261 (
The drum storage area	is located	1 2.0 mile	es east	of the	city of Col	bb.	
III. RESPONSIBLE PARTIES							
Of OWNER (If known)			02 STREE	T (Business, making, i	'esidential)		
Mr. Ed Stephens				Blacksh			
Cobb				05 ZIP CODE	06 TELEPHONE	NUMBER	
7 OPERATOR (if known and different from owner)			GA	31735	(912 853		
Same as above			08 STREET	(Business, mailing, re			
9 CITY			10 STATE	11 ZIP CODE	12 TELEPHONE	NUMBER	
3 TYPE OF OWNERSHIP (Check one)					()	1	
🗯 A. PRIVATE 🗆 B. FEDER	AL:			C. STATE	□D.COUNTY	<u>-</u>	
☐ F. OTHER:	(Specify)	(Agency name)		G. UNKN		□ E. MUNIC	CIPAL
OWNER/OPERATOR NOTIFICATION ON FILE (C	heck all that soply)	···					
☐ A. RCRA 3001 DATE RECEIVED: MON	ITH DAY YEAR	B. UNCONTROLL	ED WASTE	SITE (CERCLA 103	O DATE RECEIVED		Y
. CHARACTERIZATION OF POTENTI.	AL HAZARD				- DATE RECEIVED	MONTH DAY	YEAR O. NONE
ON SITE INSPECTION	BY (Check all)						
XYES DATE 01 / 29/ 86	☐ A. EPA ☐ E. LOCA	B. EPA L HEALTH OFFI	CONTRAC	TOR À	C. STATE	D. OTHER CO	NTRACTOR
		TOR NAME(S):		OTHER:	(\$4	recity)	
SITE STATUS (Check one)	Loo	YEARS OF OPERA					
A. ACTIVE B. INACTIVE C.	UNKNOWN	19 <u>84</u>		198		UNKNOWN	_
DESCRIPTION OF SUBSTANCES POSSIBLY PR	ESENT, KNOWN, OR A	LLEGED	GINNING YEAR	ENDING Y	EAR	OWN	·
Paint Wastes/thinners (isobutyl ketone, butyl	toluene, e acetate).	thyl benz	ene, x	ylenes, n	nethylethyl	ketone	, methyl
DESCRIPTION OF POTENTIAL HAZARD TO ENV	19014						
None - all wastes, drum	is and conta	amination	revie	wed by EP	A on 9-25-	86	
						-	
PRIORITY ASSESSMENT			 				
PRIORITY ASSESSMENT PRIORITY FOR INSPECTION (Check one. If high or m. A. HIGH B. ME	edium is checked, complete	Part 2 - Wasta informa	Wilde and Davi ?	0			

02 OF (Agency-Organization)

DNR-EPD

Hazardous Wasta Management Pro.

OS AGENCY | OB ORGANIZATION | O7 TELEP

SAU

03 TELEPHONE NUMBER

404 1656-7802 DB DATE

10 / 17/ 86

07 TELEPHONE NUMBER

404)656-7404

Jim Ussery

OA FERSON RESPONSIBLE FOR ASSESSMENT

Gilda A. Knowles J.A.X

EPA FORM 2070-12 (7 81)

Mih. Allud

VI. INFORMATION AVAILABLE FROM

OI CONTAGT

POTENTIAL HAZARDOUS WASTE SITE

I. IDENTIFICATION				
O1 STATE	02 SITE NUMBER D98141709			

SETA	PRELIMINARY ASSESSMENT		Q1 STATE	02 SITE NUMBER
PART 3 - DESCRI	RIPTION OF HAZARDOUS CONDITIONS AN	10 INCIDEI	NTS GA	D98141709
II. HAZARDOUS CONDITIONS AND INCIDENT	rs			
01 C A. GROUNDWATER CONTAMINATION 03 POPULATION POTENTIALLY AFFECTED:	02 OBSERVED (DATE:)	☐ POTENTIAL	☐ ALLEGED
	U4 NAHHATIVE DESCRIPTION			
01 B. SURFACE WATER CONTAMINATION	02 G OBSERVED (DATE:			
03 POPULATION POTENTIALLY AFFECTED:	04 NARRATIVE DESCRIPTION		☐ POTENTIAL	□ ALLEGED
01 C. CONTAMINATION OF AIR	O2 / LORDSTONE CONT.			
03 POPULATION POTENTIALLY AFFECTED:	02 L3 OBSERVED (DATE:)	☐ POTENTIAL	☐ ALLEGED
		<i>:</i>		
01 [] D. FIRE/EXPLOSIVE CONDITIONS				
03 POPULATION POTENTIALLY AFFECTED:	02 □ OBSERVED (DATE:)	□ POTENTIAL	☐ ALLEGED
		\$ \$		
01 E. DIRECT CONTACT				
03 POPULATION POTENTIALLY AFFECTED:	02 □ OBSERVED (DATE: 04 NARRATIVE DESCRIPTION)	☐ POTENTIAL	□ ALLEGED
01 [] F. CONTAMINATION OF SOIL 03 AREA POTENTIALLY AFFECTED:	02 🗆 OBSERVED (DATE:			
(Acres)	04 NARRATIVE DESCRIPTION	······································	☐ POTENTIAL	☐ ALLEGED
		-	4.	
01 🖂 G. DRINKING WATER CONTAMINATION	DO (ODOTO) TO COLUM	•		
03 POPULATION POTENTIALLY AFFECTED:	02 LI OBSERVED (DATE:)	☐ POTENTIAL	□ ALLEGED
01 () H. WORKER EXPOSURE/INJURY	02 [] OBSERVED (DATE:			
03 WORKERS POTENTIALLY AFFECTED:	04 NARRATIVE DESCRIPTION)	☐ POTENTIAL	() ALLEGED
01 I POPULATION EXPOSURE/INJURY 03 POPULATION POTENTIALLY AFFECTED:	02 (. OBSERVED (DATE: 04 NARRATIVE DESCRIPTION)	☐ POTENTIAL	C ALLEGED

SEPA

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT PART 2 - WASTE INFORMATION

I. IDENTIFICATION				
01 STATE	02 SITE NUMBER			
	D981471709			

II. WASTE S	TATES, QUANTITIES, AI	ND CHARACTER	ISTICS				·
01 PHYSICAL S	TATES (Check all that apply)	02 WASTE QUANT		03 WASTE CHARAC	TERISTICS (Check all that a	oply)	
LA. SOLID LAB. POWDE LAC. SLUDGE	R. FINES X F. LIQUID	TONS	of waste quantities andependent)	☐ C. RADIO	A. TOXIC ☐ E. SOLUBLE ☐ I. HIGHLY VOI ☐ B. CORROSIVE ☐ F. INFECTIOUS ☐ J. EXPLOSIVE ☐ C. RADIOACTIVE ☐ G. FLAMMABLE ☐ K. REACTIVE ☐ D. PERSISTENT ☐ H. IGNITABLE ☐ L. INCOMPAT		SIVE TIVE
€ D. OTHER	(Specify)	NO. OF DRUMS		IJ D. FENSI	STERT CITY RESULT	M, NOT	
III. WASTE T	YPE			<u> </u>	*****		
CATEGORY	SUBSTANCE	NAME	01 GROSS AMOUNT	02 UNIT OF MEASURI	E 03 COMMENTS		
SLU	SLUDGE		125	55-GAL		-21-7-1	
OLW	OILY WASTE			JJ-GAL	colverte	ained sludge	_and
SOL	SOLVENTS				for each w	Exact number	of drums
PSD	PESTICIDES			<u> </u>		aste is unkno	
occ	OTHER ORGANIC CI	JENICAL C			125 represe	ents total nu	umber of
10C			 		drums found	on site.	· · · · · · · · · · · · · · · · · · ·
ACD	INORGANIC CHEMIC	ALS					
				ļ			
BAS MES	BASES HEAVY METALS						
1				<u> </u>	<u> </u>		
	DUS SUBSTANCES (See A		7	r	·	, · · · · · · · · · · · · · · · · · · ·	-
01 CATEGORY	02 SUBSTANCE N	AME	03 CAS NUMBER	04 STORAGE/DIS		05 CONCENTRATION	08 MEASURE OF CONCENTRATION
SLU	toluene		108-88-3	stored a	ıt site	103,000	
<u>&</u>	ethyl benzene	!	100-41-4	11		1200	
SOL	xylenes		1330-20-7	11		16,000	
	methyl ethyl		78933	14		53,000	
	methyl isobut		108101	U U		4,800	
	butyl acetate		123-86-4	11		2,300	
							<u> </u>
Ì							

V. FEEDSTO	CKS (See Appendix for CAS Number	vel	<u> </u>				
CATEGORY	01 FEEDSTOC		02 CAS NUMBER	CATEGORY	0.155500-		
FDS	•		OE GAS HOMBEN		01 FEEDSTO	CK NAME	02 CAS NUMBER
FDS				FDS			
FDS				FDS			
FDS				FDS			
	OF INFORMATION (C)		<u> </u>	FDS	····		
	OF INFORMATION (CID.	· · · · · · · · · · · · · · · · · · ·					
GA-I	EPA State Files	Cobb,	ns Drum Stoi Georgia	rage Area			

POTENTIAL HAZARDOUS WASTE SITE PRELIMINARY ASSESSMENT


I. IDENTIFICATION				
01 STATE	02 SITE NUMBER			
CA I	D001/7170			

PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS <u>LUA LU981471709</u> II. HAZARDOUS CONDITIONS AND INCIDENTS (Continued) 01 🗆 J. DAMAGE TO FLORA 02 C OBSERVED (DATE: ____ ☐ POTENTIAL ☐ ALLEGED **04 NARRATIVE DESCRIPTION** 01 II K. DAMAGE TO FAUNA 02 G OBSERVED (DATE: _____) 04 NARRATIVE DESCRIPTION (Include name(s) of species) ☐ POTENTIAL ☐ ALLEGED 01 L. CONTAMINATION OF FOOD CHAIN 02 - OBSERVED (DATE: _____) ☐ POTENTIAL 04 NARRATIVE DESCRIPTION C ALLEGED 01 M. UNSTABLE CONTAINMENT OF WASTES 02 C OBSERVED (DATE: ____ ☐ POTENTIAL ☐ ALLEGED 03 POPULATION POTENTIALLY AFFECTED: 04 NARRATIVE DESCRIPTION 01

N. DAMAGE TO OFFSITE PROPERTY 02 GBSERVED (DATE: ____ ☐ POTENTIAL ☐ ALLEGED 04 NARRATIVE DESCRIPTION 01 🗍 O. CONTAMINATION OF SEWERS, STORM DRAINS, WV/TPs 02 🗆 OBSERVED (DATE: ☐ POTENTIAL ☐ ALLEGED 04 NARRATIVE DESCRIPTION 01 P. ILLEGAL/UNAUTHORIZED DUMPING 02 [] OBSERVED (DATE: ___ ☐ POTENTIAL **04 NARRATIVE DESCRIPTION** ☐ ALLEGED 05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR ALLEGED HAZARDS III. TOTAL POPULATION POTENTIALLY AFFECTED: 1 m1 = 403; 2 m1 = 1,079; 3 m1 = 2,257 IV. COMMENTS

V. SOURCES OF INFORMATION (Crespection references, e.g., state files, sample analysis, reports)

GA-EPD State Files - Stevens Drum Storage Area Cobb, Georgia




E. FIRONMENTAL PROTECTION DIVISION

INDUSTRIAL & HAZARDOUS WASTE MANAGEMENT PROGRAM

Complaint Record

Received By MIKE ALLRED	Log Number
Date Received 1-24-86	Duty Officer R. METHIE
ROBERT HALE Complainant: Name BILL MCC	Date Referred 1-24-8 SWREG OFFICE-341-4144 UA- WARDEN
	PRISON, AMERICUS
	, 924-1826 Area Cude 912
Alleged Source: Name UNKNOWN	·
Address	
	County
If Available: EPA I	.D. No Seq. No.
LARGE GREENHOUSE. DRUMS SAGRENHOUSE.	- TOURSE PRESENT
Details of Complaint 100 Drum	S IN PERAN GROVE
NO WATER WELLS NEWBY	AND RESIDENCES
DRUMS MAY CONTAIN PAIL HAVE BEEN ON SITE FOR	NT THINNER SCUDUE.
KOBERT HALE OF ALBANY RE	FUIDAN/FPA PITTO
COMPLAINT. REFERED TO R LANDOWNED BY ED STEVES-	ZAU RU R W-
Details Of Investigation Should Be Se	nt To:
Complainant / Other	
File: Original & 1st copy to Investi 2nd copy - Complaint Log	gating Unit



Georgia Department of Natural Resources

270 Washington Street, S.W., Jom 825, Atlanta, Georgia 30334

J. Leonard Ledbetter, Commissioner
Harold F. Reheis, Assistant Director
Environmental Protection Division

TRIP REPORT February 11, 1986

Site Name and Location:.....Stephens Drum Storage Area 2 miles east of Cobb, Sumter County, GA

Trip By:.....Steve Walker

Environmental Specialist Remedial Action Unit

Accompanied By:.....Tom Westbrook

Environmental Specialist Remedial Action Unit

Date of Trip:.....January 29, 1986

Officials Contacted:.....None Exemption 6 Personal Privacy

Reference:

Complaint received from Robert Hale of SW Region Office on January 24, 1986. Complaint alleged 100 drums of paint thinner were present in a pecan grove.

Comments:

We arrived at "The Plant Place", a greenhouse about 2 miles east of Cobb, Georgia, at 16:30 hours. Approximately 125 fifty-five gallon drums were visible in a pecan grove adjacent to the greenhouse. Most of the drums possessed a "Hazardous Materials" label. We entered the greenhouse in an attempt to locate the owner. a worker at the greenhouse, stated that the owner Mr. Ed Stephens of Cobb, GA (912)853-3205) was not there. did not know the origin of the drums, only that Mr. Stephens used them to "start fires".

Mr. Westbrook and I then proceeded to the drum storage area (Figure 2). We counted the drums and observed that at least 75% of the drums were full or almost full. Most of the drums contained "Hazardous Materials" labels with the name "Robins Air Force Base" and the number "GA1570024330". Many drums contained flammable labels which had been partially covered with yellow spray paint and some of the drums had originally been labeled "toluene" and "methyl ethyl ketone". Most of the drums had been numbered by hand with spray paint.

We selected 3 drums which did not appear to be under pressure (bulging) and opened then with a brass bung wrench. A composite sample was collected from the drums using a glass rod. The 3 drums were closed and marked with florescent pink spray paint. We were off-site by 17:00 hours.

On February 5, 1986, I contacted Mr. Stephens by telephone. He expressed his displeasure at my having entered his property without his knowledge.

He stated that he purchased the drums 2 or 3 years ago from Warner Robins Air Force Base at an auction. At that time, he was under the impression that the drums contained used paint thinner and he had planned to use the paint thinner to burn in his greenhouse furnace. After purchasing the drums and moving them to his site, he found that most contained paint sludge and were therefore unusable as fuel. Mr. Stephens stated that, in all he had burned the contents of about 8 drums containing waste oil notice.

Conclusions:

The drums appeared to have been on site for more than 6 months. Many of the drums are leaking. A solvent odor was present in the drum area. Further conclusions must await lab results.

Recommendations and Follow-up Required:

If lab results indicate that hazardous materials are present in the drums, notify the owner and request proper disposal.

Attachments:

1. Site Location Map

2. Site Sketch Map

Telephone Memorandum

4. Fact Sheet


Photographs: 2 Polaroids

Reviewed By: Joseph 7. Suromic

CSW/mcw021

cc: Lucy Justus Robert Hale

File - Stephens Drum Storage Area





SITE NAME Stephens Dom Storye
ricture No. / of 4
County Name Sumter
Date 1/19/8/ Weather on City
birection facing
Photographer Walken
Program 5, to Assessment Team
Explanation offer 125 downs
- Programme adjacent to
- He flant Place Corrections
Other Township at Cabb Ca
is 2 miles west of the site

:)



SITE NAME Stephens Drum Storage Ara Picture No. Z of
County Name Sum ten
Date 1/29/86 Weather Cool cld
Direction Facing_ /
Photographer Walker
Program S A, Tram
Explanation / 1/1/2; an chause
"Methyl Ethyl Ketone"
Paint Slosh" and Flourable
Other

て



SITE NAME Styles Storage a

Picture No. 3 of 4

County Name Sumfir

Date //cv/66 Weather

Direction Facing —

Photographer Lon/ker

Program Site Assessment Team

Explanation "Hazandas Materia

Lahla Reads —

Washing Assesse

Other CA 1-57 co 24330

SITE NAME Stephens from Storage are sicture No. 4 of 4

County Name Sumter

Date 1/20/8/2 Weather

Direction Facing

Photographer Wolker

Program S. A. Tearn

Explanation /ahe/ Moth / Ethy/

Kelone painted over wheeler

Other yellow paint

4

LAND PROTECTION BRANCH

HAZARDOUS WASTE ANALYSIS REQUEST Stevens Drum Storye Arm

NO. SAMPLES: 1 PROJECT: Cold (Tom Site COLLECTOR: Walker
CAUSTIC ACID SOLVENT	LICITO //) STATE
INFORMATION FOIND: Serve la Constate e	t a composte of liquid was tos
HAZARDOUS WASTE NOS HAZARDOUS HANDLING: WORK PRIORITY (CRITICAL NEED)	
METAL	S ANALYSPS
TOT DIS METALS (DW NO Hg) METALS (DW WITH Hg)	ep metals (DW no Hg) 🔀 100x 🗍 30x ep metals (DW with Hg)
TOT DIS TOT DIS NICKEL	EP NICKEL
SPECIFI	C ANALYSES
FLASH PT SP.COND. CYANIDE TOT. TOC CYANIDE AM. TOH	Z SOLIDS
CRCANIC	AVALYSES
PESTICITE SCREEN (EC) PCB VOLATILE ORGANICS (VOA) SPECIFIC ORGANICS: Toluras Mother The Winnity.	CC-MS BASE/NEUTRALS Dethy/ Methode / Conformation of 1986
	REMEDIAL ACTIONS UNIT
ROVED:	DEORIZED:

LABORATORY REPORT

AMPLE 1/29/46 P	ROJECT:	Coph Dr	10 5.40	თ	LECTOR:	Maker
Arres .	HW LOG NO.	1725				
ATE CC'D //30/86 CME	LABEL	DC-1				
Die 1000 Die Die Walker		ldaste liquidsludy compusite of 3 drums				
: Walker		Tiguid sludy			·	
g Backed La March LABORATORY/MANAGER		cf3 drums				
IE: 4-1-86						
RAMETERS Toluene	LAB NO.	HW1725				
Ethyl Benese	ms/Kg	103,000				
Ethyl Benzene VVlenes (total) Gethyl Ethel Ketone	/(16,000				
Grethyl Ethel Ketone	11	33.000				
Mothel Isobutyl Keta Butyl Acetate	٠١ ع	4500				
Dutyl Acetate	<u>u</u>	27004				
Flash Point	of					
· /834 /8351		360				
r Ag	-49/Kg	40.3				
A5	17	<3			 	
) ;	40.1				
cd	1 (101				
PG PG	11	10.1				
. Se) f 1 ,	<03				
J.P.	• •	< 2	· · · · · · · · · · · · · · · · · · ·			
				 		
					 	
-						
		ļ <u> </u>				
				i.		ta tu ta
				1 -		1400世代 18
				1, 1		
		 				
ARKS: * Estimated Val	, () *					
					În andere de la company	2 - 35 mg 6

not to scala

FROM: St. (/ //
TO: Mr. Ed Stephera - Ga. EPD (404)656-7404
11 /// 50 0
COMENTS: To III
coments: I called Mr. Stephens to try and of tain addit
info on the nature tarigh of the drums. Mr. Stephens st that he was quite upsat with me for going on his property
and a who was quite upset with me for going on his property
- and sampling the drums (on 1/29/86) without his property I explained that we tried to locate him at the
I explained that we tried to lacate him at the greenhouse adjacent to the site. Mr. Stephens stated II I I I wanted
to the site. Mr. Stephens stated that he hardle il
to the site. Mr. Stuphens stated that he hought the drums at an auction of Warner Robbins air base about 2 or 3 years ago. The drums were succeeded a line of the
After he had purchased they dry and the contain point think
After he had purchased the arums, most were found to
Contain paint sludge Hamilla 1
contents as he intended - 1 / 1/2 wahle to hurn the
contents as he intended - to heat the greenhouse adjacent to the site. I agreed to keep him informed at the lab data on the
Teff him in throng at I
T
Cohh, Georgia 3/735
ACTION REQUIRED:
in the diser
2/5/86
$\frac{1}{2}$
3)
5)

RECORD OF TELEPHONIC CONVERSATION

Site Investigation Program

Routing: Mike Allred Mike Allred	Date: October 17, 1986
	Time: 3:10 a.m. (p.m.)
File: Stephans Drum Storage Area	
Party Spoken To: Tim Ussery	Title: Environmental Specie
Agency/Company: Go. FPD	THE MANAGER SPACE
Address: Twin Towers C	ity: Atlanta
1elephone Number: (404) 656 - 7802 c	tate /7:
subject (file name): Stephens Drum chan	^
summary of call: I spoke with Jim Hogos	1 0 1 1 1 1 1
- 114 W ACI (ACI (ACI)	
the property and lived in the area	for the met 10 in
	es has base do yes.
Actions Required: Call Kally Mc Carty - On Emergency Rossess Hill O	Scene Conduit C
- Jan 1 1000 100 Unit of FPA 1	404) 347-393 [inquired
about clean-up]	101) Ott 313 Lindures
Signature: Hilda A. Knoulas	
Follow-up Responses/Additional Comments: Ms. Mc.Co	octurist I
EPA began clean-up of the Stephen	s Site of Gold
- The act mu total clean-up a	
completed on September 27, 1986.	of the site was
Signature: Fill (1) Know (2)	to Noteh 10 100
SIP-2	te: October 17, 1986
	5/86

SITE INSPECTION FACT SHEET

DATE: March 14, 1986

SITE NAME: Stephens Drum Storage Area

PERSON COMPLETING FORM: Steve Walker

REVIEWED BY: Mihe Albril

BACKGROUND: The site consists of ±125 fifty-five gallon drums stored in the open, in a pecan grove west of Cordele, GA. The owner, Mr. Ed Stephens of Cobb, Georgia, claims to have purchased the waste from Warner Robins Air Force Base approximately 2 years ago. Few of the drums appeared to be leaking when EPD personnel inspected the site on 1/29/86.

PARTIES ASSOCIATED WITH THE INSPECTION:

 Names of Responsible Party/Owner: Mr. Ed Stephens Cobb, GA 31735

2. Federal (EPA) and State (EPD) Officials:

EPD Contact: Ms. Lucy Justus

Phone #: 656-6905 (until 3/21/86)

656-0772 (after 3/21/86)

EPA Contact:

Phone #:

- 3. Names of Contractors: None
- 4. Names of Transporters: None
- 5. Name(s) of Disposal Site(s): Stephens Drum Storage area

WASTES INFORMATION

 List of Waste(s) including names and types: Paint wastes containing:

toluene 103,000 mg/kg
ethyl benzene 1,200 mg/kg
total xylenes 16,000 mg/kg
MEK 53,000 mg/kg
(methyl ethyl ketone)
MIK 4,800 mg/kg
(methyl isobutyl ketone)
butyl acetate 2,300 mg/kg

- Estimate(s) of Waste Amount(s):
 125 fifty-five gallon drums in various stages of fill.
- Toxicity Information (as available):
 The volatile solvents identified in the sample are toxic via ingestion, dermal absorption and inhalation.
- 4. Characteristics (physical description including physical properties under ambient conditions) and Former Usage:
 Three drums were opened and sampled by EPD personnel on 1/29/86. One of the drums contained a liquid and the two other drums contained sludges. Mr. Ed Stephens indicated in a phone conversation that most of the drums contain paint sludges.
- 5. Anticipated Environmental Pathways of Migration:
 Air route through slow evaporation. A solvent odor was present on site on 1/29/86. Very small amounts of the wastes have spilled on the ground. It is not thought that the spilled material will present a threat to ground water.
- 6. Proposed Clean-up Methods and Associated Clean-up Limits (as known): None proposed yet.

SCHEDULE. OF PROPOSED ACTIVITIES None scheduled

- 1. Start Date:
- 2. Ending Date:
- Days and Hours of Operation:

- 4. Long-term Follow-up Activities: None scheduled yet.
 - a. Description (if necessary)
 - b. Tentative dates of activities (List: Action & Date):

REASON FOR REMEDIAL ACTION(S): None scheduled yet.

Remedial Action(s) indicated resulting from:

Check One:

____Regulatory Violation - Involuntary

____Voluntary

___Emergency Cleanup

___Superfund

Comments/Description:

SITE LOCATION AND ENVIRONMENTAL SETTING

- 1. City: Cobb
- 2. County: Sum ter
- 3. Address: c/o Mr. Ed Stephens Cobb, Georgia 31735

4. Environmental Setting : (ie: physical or natural factors affecting contaminant migration): The drums are located adjacent to a greenhouse, in a pecan grove about 2 miles east of Cobb, GA. Occupied residences are located within 200 yards east of the drums and within 300 yards west of the drums.

Demographic Setting: (ie: rural, urban, etc.)
 The site is located in a rural, sparsley populated portion of Sum ter County.

INDICATED SAFETY RESTRICTION OR PRECAUTIONS

- 1. Environmental Monitoring During Cleanup Not scheduled yet.
 - a) Air -
 - b) Water -
 - c) Land -

Narrative (briefly described monitoring procedures indicating what type, how, why, etc.)

2.	Monitoring Locations(s): relationship to site) Not scheduled yet.	(describe	where	monitoring	will	occur	and
3.	Public Safety Officials(s): (name and agency)				,		
4.	Waste Handling Activities: How will materials be handle						
	Describe transportation rout		·				
	Describe decontamination pre	cautions:					
5.	Site Restrictions: Not yet Delineate area to be restrict can be identified and/or enfo	ted during :	activiti	ies relating		lineati	on

Georgia Department of Matural Resource

270 Washington Street, S.W., Room 825, Atlanta, Georgia 303

J. Leonard Ledbetter, Commissio Harold F. Reheis, Assistant Direc Environmental Protection Divis

February 21, 1986

MEMORANDUM

TO:

Jennifer Kaduck

Program Manager

Industrial and Hazardous Waste Program

FROM:

Joe Surowieç

Unit Coordinator Remedial Action Unit

SUBJ:

Stephens Drum Storage Area

Robert Hale of the Southwest Regional Office recently referred a complaint to us concerning a large number of drums. The owner of the property where the drums are stored claims that he purchased the wastes from the Robins Air Force Base "two or three years ago." Because the generator has been identified and because the generator is a TSD, we would like to refer this site to your program for follow-up.

We are awaiting the laboratory results for a composite sample that was taken from three of the drums on the site. We will forward these results to you when they are available.

JTS/mcw014 File

Georgia Department of Natural Resource

205 Butler Street, S.E., Floyd Towers East, Atlanta, Georgia 3033

J. Leonard Ledbetter, Commissione Harold F. Reheis, Assistant Directo Environmental Protection Divisio (404) 656-471

March 31, 1987

Mr. Richard A. Ferrazzuolo Emergency and Remedial Response Branch U.S. EPA, Region IV 345 Courtland Street, N.E. Atlanta, Georgia 30365

Dear Mr. Ferrazzuolo:

The following CERCLIS listed sites have been assessed by my staff to be determine if they present any potential for hazardous contamination of land, air or water:

GAD980495204 GAD981017205 GAD093333945 GAD981025109 GAD00823088 GAD981477458 GAD981477458 GAD981477458 GAD98147709 GAD981473374 GAD980847545 GAD980842819 GAD980839666 GAD980838627 Anacomp Inc. Cyanide Storage Colonial Printing Ink Company Lounty Farm County Landfill M County Farm County Landfill M County Farm County Landfill Liberty County U.S. 17 Landfill Safety-Kleen Corp. 3-013-02 Liberty County U.S. 17 Landfill Safety-Kleen Corp. 3-013-02 Liberty County U.S. 17 Landfill Liberty County U.S. 18	PRIORITY Medium Low Low Low Low Low Low None Medium Low Medium Low Medium Low Medium
--	--

The completed 2070-12 (Preliminary Assessment) forms for these sites were hand delivered to your office on March 31, 1987. Please contact me at 656-7404 if you have any questions or comments regarding these assessments.

Sincerely,

Randolph D. Williams

Program Manager

Site Investigation Program

Kandalph D. Willes

RDW: tma054

cc: John D. Taylor

File - PA Site Submissions



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION IV

JUL 1 2 1990 4WD-WPB

> Mr. John Taylor, Chief Land Protection Branch Georgia Department of Natural Resources 205 Butler Street, SW Atlanta, Georgia 30334

RE: NFRAP GEORGIA SITES

Dear Mr. Taylor:

This is to inform you that the Georgia CERCLIS sites listed below have been assigned No Further Remedial Action Planned (NFRAP) designations. The reason for the designations are the low Preliminary Hazardous Ranking System (HRS) scores calculated for each of the sites.

Please be advised that the NFRAP designations are based on information currently available and conditions and policies that currently exist.

GAD056229917 Evans Transportation Company GAD040103418 Westinghouse Air Brakes GAD980495469 Newton County Landfill GAD980559413 Morgan Falls Landfill GAD000823088 Safety-Kleen Corporation 3-013-02 GAD981471709 Stephens Drum Storage Area

It is possible that in the future our investigation of a site may be reactivated if new information or policies warrant such an action.

The site investigation on the Morgan Falls Landfill, GAD980559413 is enclosed for your information and files. A listing site evaluation (LSI-E) will be conducted for this site. The LSI-E results will be provided to you when available.

Should you have any questions, please contact me at (404)

Sincerely,

MW 7/11

Mario E. Villamarzo

Georgia Project Officer


Site Assessment Section

cc: Phil Blackwell, NUS

SITE DISCOVERY FORM

Part 1: Information necessary to add a site to CERCLIS

		,L10
ACTION: A EPA ID: <u>GRD</u> 98-147-1709		MAY 2 - ERTU
SITE NAME: <u>Stephens Drum Storage ARea</u>	Source: T	(R=250 %-0%
STREET: GA Hwy. 30	CONG DIST: 03 (potional)	Villarian, 1901
CITY: Cobb	ZIP:_81735 3/7 3	
CNTY NAME: _Sumter	CNTY CODE: 261 (
LATITUDE: 31 / 57 / 12.5 LONGITUDE	: 083 / 56 / 22.5 (optional))
INVENTORY IND: Y REMEDIAL IND: Y REMO	JVAL IND: N FED FAC IND: N	J
RPM NAME: RPM PHO	DNE: (FDC	
SITE DESCRIPTION: (optional)	\	Project Offi
_Site is located approximately_2/3 mile south o	of a point on CA lbu. 20	
that is on the western shore of Lake Blackshe		
_125 fifty-five gallon drums of paint sludges.	thinners and solvents.	
Part 2: Other site informat	ìon .	
DATE SITE FIRST REPORTED: / REPORTED	BY:	
	ty-five_gallon_drums_are_stored_	
Drums are in various stages of fill and some an	re leaking. Most drume bear it	on=site
"Hazardous Materials" or "Flammable" label on t	them. The owner of the drume is	her_a
Mr. Ed Stephens, Cobb, GA 31735. There are to	40_Occupied residences within 200	.d
the State is labina envocamin	Eaction of All .:	Pa
Contact the the state hel	er o stall in en les	g-fallallak
Contact the the state by - Equival to E 0 5 4-30-86	2 Cullin	Cliffer



ENVIRONMENTAL PROTECTION DIVISION

INDUSTRIAL & HAZARDOUS WASTE MANAGEMENT PROGRAM

Complaint Record


Received By MIKE ALLRED Log Number
Date Received 1-24-86 Duty Officer R. METHIE
ROBERT HALE SWREG OFFICE-3
Complainant: Name DICE MICCING - WARDEN
Address Junter Co Prison, AMERICUS
Phone No. 924-6066, 924-1826 Area Cude 912
Alleged Source: Name UNKNOUN
Address
County
If Available: EPA I.D. No Seq. No.
CARGE CREENHOUSE, DRUMS SHOULD BEVISIBLE FROM GLEEN HOUSE. Details of Complaint
100 DRUMS IN PETAN (IRNIE
SOME LEAKING - NO IMMED THREAT/TARGETS NO WATER WELLS NEARBY & NO RESIDENCES
DRUMS MAY CONTAIN PAINT THINNER/ SCUDGE.
HAVE BEEN ON SITE FUR SOMETIME. ROBERT HALE OF ALBANY REGION/EDD REFERRED
COMPLAINT. REFERRED TO RAU BY R. METHIER LANDOWNED BY ED STEVES - NO OTHER INFO AVAIL.
Details Of Investigation Should Be Sent To:
Complainant // Other
File: Original & 1st copy to Investigating Unit 2nd copy - Complaint Log

Roud: 4-30-86

SITE DISCOVERY FORM

Part 1: Information necessary to add a site to CERCLIS

ACTION: A	
EPA ID:	
SITE NAME: Stephens Drum Storage ARea	SOURCE: [(R=EPA, T=S
STREET: GA Hwy. 30	CONG DIST: 03 (optional)
CITY: Cobb	ZIP: 81735
CNTY NAME: _Sumter	CNTY CODE: 261 (optional)
LATITUDE: 31 / 57 / 12.5 LONGITUDE:	083 / 56 / 22.5 (optional)
INVENTORY IND: Y REMEDIAL IND: Y REMOV	/AL IND: N FED FAC IND: N
RPM NAME: RPM PHON	√E: (EPA Project Of
SITE DESCRIPTION: (optional)	
Site is located approximately 2/3 mile south of	f_a_point_on_GA_Hwy30
that is on the western shore of Lake_Blackshear	Site_has_approximately
_125 fifty-five gallon drums of paint sludges, t	hinners and solvents
Part 2: Other site informati DATE SITE FIRST	orı .
	EA:
REASON FOR LISTING:Approximately_125_fift	•
_Drums_are_in_various_stages_of_fill_and_some_ar	
_"Hazardous Materials" or "Flammable" label on t	hem. The owner of the drums is a
_Mr. Ed_Stephens, Cobb, GA 31735. There are two	
_of_the_site; both_are_believed_to_be_using_well:	s
the Sisting thing in your	Faction at the sit, those
Contract the the whater has	Red Marie Legata.
eck w/state 1	



ENVIRONMENTAL PROTECTION DIVISION


INDUSTRIAL & HAZARDOUS WASTE MANAGEMENT PROGRAM

Complaint Record

Received By MINEALLRED Log Number
Date Received 1-24-86 Duty Officer R. METHIER
ROBERT HALE SWREG OFFICE- 341-4144 Complainant: Name BILL MCCLUG - WARDEN
Address JUMTER COPRISON, AMERICUS
Phone No. 924-6066, 924-1826 Area Cude 912
Alleged Source: Name UNKNOWN
Address
County
If Available: EPA I.D. No Seq. No
LARGE GREENHOUSE. DRUMS SHOULD BEVISIBLE FROM. GLEENHOUSE.
Details of Complaint 100 DRUMS IN PERAN GROVE
SOME LEAKING-NO IMMED THREAT/TARGETS NO WATER WELLS NEARBY & NO RESIDENCES
DRUMS MAY CONTAIN PHINT THINNER/SCUDUE.
HAVE BEEN ON SITE FUR SOMETIME. ROBERT HALE OF ALBANY REGION/EDD REFERRED
COMPLAINT. REFERRED TO RAY BY R METHIER LANDOWNED BY ED STEVES-NO OTHER INFOAVAIL.
Details Of Investigation Should Be Sent To:
Complainant /7 Other
File: Original & 1st copy to Investigating Unit 2nd copy - Complaint Log



1927 LAKESIDE PARKWAY SUITE 614 TUCKER, GEORGIA 30084 404-938-7710



Site Disposition:

EPA Project Manager:

March 22, 1990

Mr. A. R. Hanke
Site Investigation and Support Branch
Waste Management Division
Environmental Protection Agency
345 Courtland Street, N. E.
Atlanta, Georgia 30365

Subject:

Screening Site Inspection, Phase I Stephens Drum Storage Area Cobb, Sumter County, Georgia EPA ID No. GAD981471709 TDD No. F4-9001-99

Dear Mr. Hanke:

FIT 4 was tasked to conduct a Screening Site Inspection at Stephens Drum Storage Area located in Cobb, Sumter County, Georgia. Phase I of the inspection included a review of state and EPA file material, a target survey, and an offsite reconnaissance of the property and surrounding area.

Stephens Drum Storage Area is located on Georgia Highway 30 about 2 miles east of Cobb, Georgia, near Lake Blackshear (Ref. 1). The property, owned by Ed Stephens, is located in a rural, sparsely populated area. The storage area is on the western shore of Lake Blackshear surrounded by pecan groves and a scattering of lakeside residences (Refs. 1, 2).

Some time between 1983 and 1984, Mr. Stephens purchased approximately 125 55-gallon drums of paint wastes and thinners from Warner Robins Air Force Base in Warner Robins, Georgia. The drums were stored in the open in a pecan grove. He intended to use the contents to heat a greenhouse on the property (Ref. 2). Soil contamination may have occurred because some of the drums were reportedly leaking during an inspection by the Georgia Environmental Protection Division (EPD) on January 29, 1986 (Ref. 3).

Approximately eight drums of paint thinner and waste oil were burned in Mr. Stephens's greenhouse furnace. During the investigation by the Georgia EPD in January 1986, state officials identified a solvent odor present in the drum area. A composite sample from three drums was taken, and results indicated that hazardous materials were present (Refs. 2, 3).

Sample analysis revealed the presence of toluene, ethyl benzene, xylenes, methyl ethyl ketone, methyl isobutyl ketone, and butyl acetate (Ref. 3). The U.S. Environmental Protection Agency, Emergency Response Unit removed the drums on September 25 - 27, 1986. During the offsite reconnaissance in January 1990, no fencing or warning signs were observed around the storage area and due to the earlier cleanup, no drums were present or identified at the facility (Refs. 4, 5).

Mr. A.R. Hanke Environmental Protection Agency TDD No. F4-9001-99 March 22, 1990 - page two

Mr. Stephens never requested and was never issued any type of permit for the storage area (Refs. 6, 7).

The Stephens Drum Storage Area is located in the Fall Line Hills District within the Coastal Plain Physiographic Province (Ref. 8, pp. 3, 4). This region consists of complexly interbedded sand, silt and clay layers, which dip toward the coast (Ref. 8, p. 4). The area is characterized by topography that is highly dissected by stream erosion (Ref. 8, p. 3). Sumter County has a temperate climate with mild winters and warm, humid summers (Ref. 8, p. 4). The total annual precipitation averages about 49 inches with a net annual precipitation of 5 inches (Refs. 8, p. 4; 9, pp. 43, 63). The 1-year, 24-hour rainfall is approximately 3.5 inches (Ref. 10, p. 93).

The geology of the Cobb area consists of a sequence of stratified sediments deposited upon an igneous and metamorphic bedrock. The units underlying the storage area, in descending order, are the Claiborne Group, the Wilcox Group, Oconee Group, Clayton formation and the upper Cretaceous sediments (Ref. 8, plate 1). Three aquifer systems are present in the storage area, and all of them are confined (Ref. 8, p. 8).

The Claiborne aquifer is the shallowest aquifer encountered in the area and is located at 150 feet below land surface (Ref. 8, p. 13). This aquifer is composed of sand, silt and clay sediments that are approximately 200 feet thick (Ref. 8, pp. 13, 15). The impermeable clays of the upper Lisbon Formation form a confining layer that separates the Claiborne aquifer from the surface and has a hydraulic conductivity of 1.0 x 10⁻⁷ cm/sec (Refs. 8, p.8; 11).

Beneath the Claiborne aquifer is the Clayton aquifer, located 350 feet below land surface, which is composed primarily of limestone (Ref. 8, pp. 8, 9). The Clayton aquifer is confined above by the clay-rich layers in the upper Clayton Formation and Nanafalia Formation, and below by the silt and clay of the lower Clayton and upper Province Sand formations (Ref. 8, p. 8).

Below the Clayton aquifer is the Providence Sand aquifer in the Cretaceous aquifer system. Other aquifers exist in the system in deeper formations (Ref. 8, p. 8). The Providence Sand aquifer is located 500 feet below land surface and is a good source of groundwater (Ref. 8, p. 8).

Surface water drainage from the storage area is south toward Lake Blackshear. The drainage would flow overland approximately 800 feet before entering Lake Blackshear. Lake Blackshear continues south for approximately 5 miles before entering the Flint River. The Flint River continues further south for the remainder of the 15-mile migration pathway (Ref. 12). There are no permitted surface water intakes along the 15-mile migration pathway; however, recreational and commercial fishing as well as swimming and boating do occur along the route (Refs. 13, 14).

All residents within a 4-mile radius obtain water from private wells. The closest well is located approximately 200 feet west of the site. It is completed at a depth of 165 feet (Ref. 4). A house count from USGS topographic maps identified approximately 488 houses within a 3-mile radius using private wells as the source of drinking water (Ref. 12). Depths of other drinking water wells in the vicinity of the site range between 120 and 160 feet (Ref. 15).

Mr. A.R. Hanke Environmental Protection Agency TDD No. F4-9001-99 March 22, 1990 - page three

Although the ranges of some endangered or threatened species include the state of Georgia, no critical habitats are designated in Sumter County (Ref. 16).

Because of the limited permeability of the confining layer between the surface and the aquifer of concern, and the lack of surface water targets, FIT 4 recommends that no further action be planned for Stephens Drum Storage Area. If you have any comments or questions about this Phase I SSI, please contact me at NUS Corporation.

Very truly yours,

Alvin L. Williams

Project Manager

ALW/gwn

Enclosures

cc: Janice Thomas

Approved:

Professional Geologist

REFERENCES

- 1. Potential Hazardous Waste Site Preliminary Assessment (EPA Form 2070-12) and attachments for Stephens Drum Storage Area. Filed by Gilda A. Knowles, Georgia Department of Natural Resources, Environmental Protection Division, October 17, 1986.
- 2. Report of Trip to Stephens Drum Storage Area on January 29, 1986; filed by Steve Walker, Georgia Department of Natural Resources, Remedial Action Unit, February 11, 1986.
- 3. Site Inspection Fact Sheet for Stephens Drum Storage Area on March 14, 1986; filed by Steve Walker, Georgia Environmental Protection Division.
- 4. Jim Ussery, Georgia Environmental Protection Division, telephone conversation with Gilda A. Knowles, Georgia Department of Natural Resources, October 17, 1986. Subject: Cleanup activities at Stephens Drum Storage Area.
- 5. NUS Corporation Field Logbook No. F4-1965 for Stephens Drum Storage Area, TDD No. F4-9001-99. Documentation of facility reconnaissance, January 24, 1990.
- 6. U.S. Environmental Protection Agency, Facility Index System (FINDS), Region IV, printout for Stephens Drum Storage Area, EPA ID No. GAD981471709, August 8, 1989.
- Sue Matzuras, Georgia Environmental Protection Division, telephone conversation with Alvin Williams, NUS Corporation, February 13, 1990. Subject: Regulatory Status, Stephens Drum Storage Area.
- 8. Stephen S. McFadden and D. Dennis Perriello, <u>HydroGeology of The Clayton and Claiborne Aquifers in Southwestern Georgia</u>, Circular 55 (Georgia Geologic Survey, Atlanta 1983).
- 9. U.S. Department of Commerce, <u>Climate Atlas of the United States</u> (Washington, D.C.: GPO, June 1986). Reprint: 1983, National Oceanic and Atmospheric Administration, pp. 43, 63.
- 10. U.S. Department of Commerce, <u>Rainfall Frequency Atlas of the United States</u>, Technical Paper No. 40 (Washington, D.C.: GPO 1963), p. 93.
- 11. U.S. Environmental Protection Agency, <u>Uncontrolled Hazardous Waste Site Ranking System: A Users Manual</u> (HW-10), originally published in the July 16, 1982, <u>Federal Register</u> (Washington, D.C.: GPO 1984), p. 15.
- 12. U.S. Geological Survey, 7.5 minute series Topographic Quadrangle Maps of Georgia: Drayton 1972, Leslie 1973, Cobb 1977 (Photoinspected 1983), Cordele 1974 (Photorevised 1987), scale 1:24,000.
- 13. Georgia Environmental Protection Division, Water Availability and Use Flint River Basin, (1984).
- 14. Ann Ushery, Georgia Department of Natural Resources-Game and Fish, telephone conversation with Alvin Williams, NUS Corporation, February 12, 1990. Subject: Activity at Lake Blackshear.
- 15. Mr. Peeples, Southeastern Drilling Company, telephone conversation with Alvin Williams, NUS Corporation, February 12, 1990. Subject: Private well depth in and around Cobb, Georgia.

U.S. Fish and Wildlife Service, <u>Endangered and Threatened Species of the United States</u> (Atlanta, Georgia, 1988), pp. 1, 2. 16.

RECONNAISSANCE CHECKLIST FOR HRS2 CONCERNS

Instructions: Obtain as much "up front" information as possible prior to conducting fieldwork. Complete the form in as much detail as you can, providing attachments as necessary. Cite the source for all information obtained.

Site Name: Stephen Drum Storage

City, County, State: Cobb, Sumter County, Georgia

EPA ID No.: GAD981471709

Person responsible for form: Alvin L. Williams

Date: 1-24-90

Air Pathway

Describe any potential air emission sources onsite: Potentially contaminated surface soil.

Identify any sensitive environments within 4 miles: None

Identify the maximally exposed individual (nearest residence or regularly occupied building - workers do count): Several houses in vicinity of the facility.

Groundwater Pathway

Identify any areas of karst terrain: None

Identify additional population due to consideration of wells completed in overlying aquifers to the AOC. None

Do significant targets exist between 3 and 4 miles from the site? The townships of Cobb and Conley, GA; Georgia Veteran's Memorial State Park.

Is the AOC a sole source aquifer according to Safe Drinking Water Act? (i.e. is the site located in Dade, Broward, Volusia, Putnam, or Flager County, Florida): No

Surface Water Pathway

Are there intakes located on the extended 15-mile migration pathway? No

Are there recreational areas, sensitive environments, or human food chain targets (fisheries) along the extended pathway? Lake Blackshear is used for recreational and commercial fishing.

Onsite Exposure Pathway

Is there waste or contaminated soil onsite at 2 feet below land surface or higher? unknown

Is the site accessible to non-employees (workers do <u>not</u> count)? The site is in an open pecan grove with no barriers.

Are there residences, schools, or day care centers onsite or in close proximity? There are several permanent houses in close proximity of the facility.

Are there barriers to travel (e.g., a river) within one mile? Lake Blackshear is approximately 800 feet.

HAZARD RANKING SYSTEM SCORING SUMMARY

FOR

STEPHEN'S DRUM STORAGE AREA EPA SITE NUMBER GAD981471709 COBB SUMTER COUNTY. GA EPA REGION: 4

SCORE STATUS: IN PREPARATION

SCORED BY ALVIN WILLIAMS
OF NUS CORPORATION
ON 02/05/90

DATE OF THIS REPORT: 03/26/90 DATE OF LAST MODIFICATION: 03/26/90

GROUND WATER ROUTE SCORE: 28.57
SURFACE WATER ROUTE SCORE: 6.71
AIR ROUTE SCORE: 0.00

MIGRATION SCORE : 16.97

HRS GROUND WATER ROUTE SCORE

2. ROUTE CHARACTERISTICS DEPTH TO WATER TABLE 150 FEET 6 FEET DEPTH TO BOTTOM OF WASTE 6 FEET DEPTH TO AQUIFER OF CONCERN 144 FEET 1 8 PRECIPITATION 49.0 INCHES EVAPORATION 44.0 INCHES NET PRECIPITATION 5.0 INCHES 2 6 PERMEABILITY 1.0X10-7 CM/SEC 0 0 PHYSICAL STATE 3 3 TOTAL ROUTE CHARACTERISTICS SCORE: 7		CATEGORY/FACTOR	₹	RAW DAT	A	ASN. VALUE	SCORE
DEPTH TO WATER TABLE DEPTH TO BOTTOM OF WASTE DEPTH TO AGUIFER OF CONCERN PRECIPITATION PRECIPITATION A4.0 INCHES NET PRECIPITATION A4.0 INCHES NET PRECIPITATION A4.0 INCHES PERMEABILITY A5.0 INCHES A5.0 INCHES A6.0 I	1. n	OBSERVED RELEAS	BE	NO	**************************************	(_)	0
DEPTH TO BOTTOM OF WASTE	2.	ROUTE CHARACTES	RISTICS		e van sel rod verrê û pên ira û rêmadê û day rên û dewe y	particle setting a processor at which, and at the a public section are cast of technical con-	***************************************
PRECIPITATION 49.0 INCHES EVAPORATION 44.0 INCHES NET PRECIPITATION 5.0 INCHES 2 PERMEABILITY 1.0X10-7 CM/SEC 0 PHYSICAL STATE 3 3 CONTAINMENT 4 3 1 CU. YDS 2 CONTAINMENT 5 2 20 CONTAINMENT 5 2 20 CONTAINMENT 5 2 20 CONTAINMENT 6 1 200 FEET 30 CONTAINMENT 7 200 FEET 30							
EVAPORATION 44.0 INCHES NET PRECIPITATION 5.0 INCHES 2 PERMEABILITY 1.0X10-7 CM/SEC 0 0 PHYSICAL STATE 3 9 TOTAL ROUTE CHARACTERISTICS SCORE: 7 3. CONTAINMENT 3 3 3 4. WASTE CHARACTERISTICS TOXICITY/PERSISTENCE:ASSIGNED VALUE, 18 18 WASTE QUANTITY CUBIC YDS 0 0 DRUMS 125 GALLONS 0 0 TOTAL 31 CU. YDS 2 2 TOTAL WASTE CHARACTERISTICS SCORE: 20 5. TARGETS GROUND WATER USE 3 9 DISTANCE TO NEAREST WELL 200 FEET AND TOTAL POPULATION SERVED 1934 PERSONS NUMBER OF HOUSES 488 NUMBER OF HOUSES 488 NUMBER OF PERSONS 0 NUMBER OF IRRIGATED ACRES 0		DEPTH TO AQUIFE	ER OF CONCERN	1 444	FEET	1	2
PERMEABILITY 1.0X10-7 CM/SEC 0 OPHYSICAL STATE 3 9 TOTAL ROUTE CHARACTERISTICS SCORE: 7 3. CONTAINMENT 3 3 4. WASTE CHARACTERISTICS TOXICITY/PERSISTENCE:ASSIGNED VALUE, LB 13 WASTE QUANTITY CUBIC YDS 0 DRUMS 125 GALLONS 0 TONS 0 TOTAL 31 CU. YDS 2 2 TOTAL WASTE CHARACTERISTICS SCORE: 20 5. TARGETS GROUND WATER USE 3 9 DISTANCE TO NEAREST WELL AND TOTAL POPULATION SERVED 1854 PERSONS NUMBER OF HOUSES 4BB NUMBER OF CONNECTIONS 0 NUMBER OF CONNECTIONS 0 NUMBER OF CONNECTIONS 0 NUMBER OF IRRIGATED ACRES 0							
PHYSICAL STATE TOTAL ROUTE CHARACTERISTICS SCORE: 3. CONTAINMENT 4. WASTE CHARACTERISTICS TOXICITY/PERSISTENCE:ASSIGNED VALUE, L8 WASTE QUANTITY CUBIC YDS DRUMS 125 GALLONS OTONS OTONS OTONS OTONS TOTAL TOTAL 31 CU. YDS 2 ENDING SCORE: 20 TOTAL WASTE CHARACTERISTICS SCORE: 20 TOTAL WASTE CHARACTERISTICS SCORE: 3 9 DISTANCE TO NEAREST WELL AND TOTAL POPULATION SERVED NUMBER OF HOUSES NUMBER OF PERSONS NUMBER OF FRESONS NUMBER OF IRRIGATED ACRES OTONS TOTAL TARSETS SCORE: 1854 PERSONS NUMBER OF CONNECTIONS ONUMBER OF IRRIGATED ACRES OTONS		NET PRECIPITATI	ON	5.0	INCHES	2	,
TOTAL ROUTE CHARACTERISTICS SCORE: 3. CONTAINMENT 4. WASTE CHARACTERISTICS TOXICITY/PERSISTENCE:ASSIGNED VALUE, 18 WASTE QUANTITY CUBIC YDS GALLONS GALLONS TONS O TOTAL 31 CU. YDS 2 TOTAL WASTE CHARACTERISTICS SCORE: 20 TOTAL WASTE CHARACTERISTICS SCORE: 3 99 DISTANCE TO NEAREST WELL AND MATRIX VALUE AND TOTAL POPULATION SERVED NUMBER OF HOUSES NUMBER OF CONNECTIONS NUMBER OF IRRIGATED ACRES O TOTAL TARGETS O TOTAL TARGETS O TOTAL TARGETS T		PERMEABILITY		1.0110-7	CM/SEC	0	O
3. CONTAINMENT 3 3 4. WASTE CHARACTERISTICS TOXICITY/PERSISTENCE:ASSIGNED VALUE, 18 WASTE QUANTITY CUBIC YDS O DRUMS 125 GALLONS O TONS O TONS O TONS O TONS O TONS O TOTAL 31 CU. YDS 2 2 TOTAL WASTE CHARACTERISTICS SCORE: 20 5. TARGETS GROUND WATER USE 3 9 DISTANCE TO NEAREST WELL 200 FEET AND MATRIX VALUE 30 30 TOTAL POPULATION SERVED 1854 PERSONS NUMBER OF PERSONS O NUMBER OF PERSONS O NUMBER OF CONNECTIONS O NUMBER OF IRRIGATED ACRES O		PHYSICAL STATE				3	3
4. WASTE CHARACTERISTICS TOXICITY/PERSISTENCE:ASSIGNED VALUE, 18 WASTE QUANTITY CUBIC YDS O DRUMS 125 GALLONS O TONS O TONS O TOTAL 31 CU. YDS 2 2 TOTAL WASTE CHARACTERISTICS SCORE: 20 5. TARGETS GROUND WATER USE 3 9 DISTANCE TO NEAREST WELL 200 FEET AND MATRIX VALUE 30 30 TOTAL POPULATION SERVED 1854 PERSONS NUMBER OF HOUSES 488 NUMBER OF PERSONS O NUMBER OF CONNECTIONS O NUMBER OF IRRIGATED ACRES O		TOTAL ROUTE CHA	RACTERISTICS S	CORE:			7
TOXICITY/PERSISTENCE:ASSIGNED VALUE, 18 WASTE QUANTITY CUBIC YDS ODRUMS 125 GALLONS OTONS	3,	CONTAINMENT		and the contract of the contra			3
WASTE QUANTITY CUBIC YDS O DRUMS 125 GALLONS O TONS O TOTAL 31 CU. YDS 2 2 TOTAL WASTE CHARACTERISTICS SCORE: 20 5. TARGETS GROUND WATER USE 3 9 DISTANCE TO NEAREST WELL 200 FEET AND MATRIX VALUE 30 30 TOTAL POPULATION SERVED 1854 PERSONS NUMBER OF PERSONS O NUMBER OF PERSONS O NUMBER OF IRRIGATED ACRES O	ć., "	WASTE CHARACTER	:ISTICS	itt pallitikusi kadin olis tud ohikusikkasininimusa sakabilaya az-ang guing y	**************************************	M. 1970 March 1971 Mar	
DRUMS 125 GALLONS 0 TONS 0 TOTAL 31 CU. YDS 2 2 TOTAL WASTE CHARACTERISTICS SCORE: 20 5. TARGETS GROUND WATER USE 3 9 DISTANCE TO NEAREST WELL 200 FEET AND MATRIX VALUE 30 30 TOTAL POPULATION SERVED 1854 PERSONS NUMBER OF HOUSES 488 NUMBER OF PERSONS 0 NUMBER OF CONNECTIONS 0 NUMBER OF IRRIGATED ACRES 0		TOXICITY/PERSISTENCE:ASSIGNED VALUE,18					
TOTAL WASTE CHARACTERISTICS SCORE: 5. TARGETS GROUND WATER USE DISTANCE TO NEAREST WELL AND MATRIX VALUE AND TOTAL POPULATION SERVED NUMBER OF HOUSES NUMBER OF HOUSES NUMBER OF PERSONS NUMBER OF CONNECTIONS NUMBER OF IRRIGATED ACRES TOTAL TARGETS COORE.		WASTE QUANTITY	DRUMS GALLONS	125 0			
5. TARGETS GROUND WATER USE DISTANCE TO NEAREST WELL AND MATRIX VALUE TOTAL POPULATION SERVED NUMBER OF HOUSES NUMBER OF PERSONS NUMBER OF PERSONS NUMBER OF CONNECTIONS NUMBER OF IRRIGATED ACRES TOTAL TARGETS COORE.			TOTAL	31	CU. YDS	3 2	2
GROUND WATER USE DISTANCE TO NEAREST WELL AND AND MATRIX VALUE 30 TOTAL POPULATION SERVED 1854 PERSONS NUMBER OF HOUSES 488 NUMBER OF PERSONS 0 NUMBER OF CONNECTIONS 0 NUMBER OF IRRIGATED ACRES 0		TOTAL WASTE CHAI	RACTERISTICS S	CORE;	•		20
DISTANCE TO NEAREST WELL 200 FEET AND MATRIX VALUE 30 30 TOTAL POPULATION SERVED 1854 PERSONS NUMBER OF HOUSES 488 NUMBER OF PERSONS 0 NUMBER OF CONNECTIONS 0 NUMBER OF IRRIGATED ACRES 0	5.	TARGETS					***************************************
AND MATRIX VALUE 30 30 TOTAL POPULATION SERVED 1854 PERSONS NUMBER OF HOUSES 488 NUMBER OF PERSONS 0 NUMBER OF CONNECTIONS 0 NUMBER OF IRRIGATED ACRES 0		GROUND WATER USI				3	9
TOTAL TARGETS SCORE:		AND TOTAL POPULATIO NUMBER OF HOL NUMBER OF PE NUMBER OF COL	N SERVED JSES RSONS NNECTIONS	MATRIX VA 1954 488 0 0	L.UE		30
	D. 1945-1-1 207	TOTAL TARGETS SO	CORE:				39

SITE: STEPHEN'S DRUM STORAGE AREA

HRS SURFACE WATER ROUTE SCORE

2. F	DBSERVED RELEASI ROUTE CHARACTER BITE LOCATED IN BITE WITHIN CLOSE FACILITY SLOPE	ISTICS	NO		(<u>``</u>)	0
9	SITE LOCATED IN SITE WITHIN CLOS		r braganina wara sa magan sanag isi fina gaman ranasanya sasa basa ma			
S (=	SITE WITHIN CLO	COLUMN A COMPUTATOR				/ BOOK > 2 COLUMN TO COLUM
	INTERVENING SLO	BED BASIN	NO NO 1.0 1.0		o	0
i	24-HOUR RAINFALL	.	3.5	INCHES	3	3
Ţ	DISTANCE TO DOW	N-SLOPE WATER	800	FEET	3	6
F	PHYSICAL STATE			9		3
"[TOTAL ROUTE CHAI	RACTERISTICS SO	CORE:			12
Э. С	CONTAINMENT			3		3
4. 4	VASTE CHARACTER	ISTICS	nessel et redakt bled et i Makk til redaktion i selv inden segmet inn	d a to many different and a second control of the property of the second		
T	OXICITY/PERSIST	ENCE:ASSIGNED	VALUE,18			18
la	JASTE QUANTITY	CUBIC YDS DRUMS GALLONS TONS	0 125 0 0			
		TOTAL	31	CU. YDS	S 2	2
T	OTAL WASTE CHAF	RACTERISTICS SC	CORE;			20
5. 1	TARGETS		APPROXIMATION (ASSESSED) 200 (100 CH) 100 (100 CH) 100 CH)	Marie com provide surfaces with a simulation of the second section of the section of t	Principal and the second se	**************************************
C	BURFACE WATER US	BE.			2	Ó
Ţ	DISTANCE TO SENS COASTAL WETLA FRESH-WATER (CRITICAL HABI	NDS JETLANDS	MENTS NONE NONE NONE		0	0
Ι	DISTANCE TO STATO ISTANCE TO WATE AND AND FOR AND FOR AND FOR AND FOR AND	R SUPPLY INTAK I SERVED JSES RSONS NNECTIONS	SOO E > 1 MATRIX VA O O O O	MILE	•	Ů
	TOTAL TARGETS SO	OORE:				6